Weathertzetion Assistance

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0877/1

Work Order Type: Weatherization

Audit Name: 17017UC-0877

CLIENT INFORMATION

Client ID: 17017UC-0877

AGENCY INFORMATION

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Fax:

Address: 3313 Williams Enterprise Drive

Cookeville, TN 38506 Email Address:

| Company Name & License Number: | |
|--------------------------------|--|
| Contractor's Signature: | |

COMMENT

1997 MOBILE HOME

| Measure 1 Seal Ducts | | | | | | Inspected | | | |
|----------------------|---|--|-------------------------------------|---------|--------------|-----------|-----|------------|-----------|
| C | | ND REPAIR DUCTS X9 REGISTER REPLACEM | ENTX2 | | | | | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Insulation | Duct sealing (setup cost) | Each | 1 | | | | | |
| 10 | Miscellaneous Supplies | Duct Sealing | Each | 1 | | | | | |
| C | Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | Measur | e Sub Total: | | , | Sub Total: | |
| | | | | | | | | | |
| | TRIM RI INSTAL | eral Air Sealing INTERIOR 10 WINDOW EPLACEMENT 19 FT FO L 2 DOOR SWEEPS IERSTRIP 2 DOORS USI | R DOOR | | | HERSTF | RIP | | Inspected |
| | comment CAULK TRIM RI INSTAL | INTERIOR 10 WINDOW EPLACEMENT 19 FT FO L 2 DOOR SWEEPS IERSTRIP 2 DOORS USI | R DOOR | ONE E | BULB WEAT | HERSTF | | Actual | Inspected |
| C | Comment CAULK TRIM RI INSTAL WEATH Material / Labor | INTERIOR 10 WINDOW EPLACEMENT 19 FT FO L 2 DOOR SWEEPS | R DOOR | | BULB WEAT | HERSTF | Qty | | |
| <i>C</i> | comment CAULK TRIM RI INSTAL WEATH Material / Labor Insulation Miscellaneous | INTERIOR 10 WINDOW EPLACEMENT 19 FT FO L 2 DOOR SWEEPS IERSTRIP 2 DOORS USI Description / Comment General air sealing | R DOOR NG SILIC <i>Unit</i> s | ONE E | BULB WEAT | HERSTF | | Actual | |
| # 1 | comment CAULK TRIM RI INSTAL WEATH Material / Labor Insulation | INTERIOR 10 WINDOW: EPLACEMENT 19 FT FO L 2 DOOR SWEEPS IERSTRIP 2 DOORS USI Description / Comment General air sealing (setup cost) | R DOOR NG SILIC Units Each | ONE E | BULB WEAT | HERSTF | | Actual | |
| # 1 | Comment CAULK TRIM RI INSTAL WEATH Material / Labor Insulation Miscellaneous Supplies | INTERIOR 10 WINDOW: EPLACEMENT 19 FT FO L 2 DOOR SWEEPS IERSTRIP 2 DOORS USI Description / Comment General air sealing (setup cost) | R DOOR NG SILIC Units Each | ONE E | BULB WEAT | HERSTF | | Actual | |
| # 1 | Comment CAULK TRIM RI INSTAL WEATH Material / Labor Insulation Miscellaneous Supplies | INTERIOR 10 WINDOW: EPLACEMENT 19 FT FO L 2 DOOR SWEEPS IERSTRIP 2 DOORS USI Description / Comment General air sealing (setup cost) | R DOOR NG SILIC Units Each | ONE E | BULB WEAT | HERSTF | | Actual | |
| # 1 | Comment CAULK TRIM RI INSTAL WEATH Material / Labor Insulation Miscellaneous Supplies | INTERIOR 10 WINDOW: EPLACEMENT 19 FT FO L 2 DOOR SWEEPS IERSTRIP 2 DOORS USI Description / Comment General air sealing (setup cost) | NG SILIC Units Each Each | 2ty 1 1 | BULB WEAT | HERSTF | Qty | Actual | |

| 1 Insulation D | Pescription / Comment WH Tank Insulation WH Tank Insulation | <i>Units</i> Each | Qty | Estimated Unit Cost | Total | | Actual | |
|--------------------------|---|----------------------|-----------------|---------------------|-------------|-----|------------|-----------|
| 1 Insulation D 2 Labor D | WH Tank Insulation | | _ | Unit Cost | Total | 04. | | |
| 2 Labor D | | Each | | | rotar | Qty | Unit Cost | Total |
| | WH Tank Insulation | | 1 | | | | | |
| Other Detail | | Each | 1 | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | . Out Total | | | Sub Total: | |
| | | | Measur | e Sub Total: | | • | Sub Total. | |
| Measure 4 DWH P Comment | ipe Insulation | | | Componen | | | | Inspected |
| # Matarial/Labor D | one windian / Comment | Unita | <u> </u> | Estimated | | | Actual | Total |
| | WH Pipe Insulation | <i>Units</i> Each | Qty 1 | Unit Cost | Total | Qty | Unit Cost | Total |
| | WH Pipe Insulation | Each | 1 | | | | | |
| Other Detail | • | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | | , | Sub Total: | |
| | | | | | | | | |
| Field Notes: | | | | | | | | |

| | Measure 5 Sett | back [heating] | | | Componen | its | | | Inspected | |
|---|----------------------|--|---------|--------|------------------|-------|----------|------------------|-----------|--|
| C | comment BID AS | TUNE UP | | | | | | | | |
| | | | | | Estimated | | Actual | | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| 1 | Heating Equipment | Setback thermostat | Each | 1 | | | | | | |
| 2 | Labor | Setback thermostat | Each | 1 | | | | | | |
| (| Other Detail |] [| | | | | - | | | |
| L | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | | |
| | comment AUDITO | y Fiberglass Loose OR STATED: MOBILE HO | OME UND | ER BE | Componen | | | | Inspected | |
| | FIBERO | GLASS 48 SQ. FT | | | Estimated | 1 | | Actual | | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total | |
| | Insulation | Floor Insulation - Fbergls,Blwn | Bag | 28 | | | | | | |
| 2 | Labor | Floor Insulation - Fbergls,Blwn | Bag | 28 | | | | | | |
| 3 | Other | Floor Insulation - Fbergls,Blwn | Each | 1 | | | | | | |
| C | Other Detail | | | | | | | | 1 | |
| L | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | Measur | e Sub Total: | | | Sub Total: | | |
| | Field Notes: | | | | | | | | | |

| | | s Storm Windows | 4 | | Compone | ents A | 1 | | | Inspected |
|---|-------------------------|-------------------------|-----------|----------|-------------|------------|----|------|------------|-----------|
| C | comment 1 STOR | M WINDOW SIZE 32X54 | 4 | | Estimat | od | | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | | al | Qty | Unit Cost | Total |
| | Windows | Glass storm windows | SqFt | 24 | | | | | | |
| _ | Lobor | Class storm windows | SaE+ | 24 | |] [| | | | |
| | Labor | Glass storm windows | SqFt | 24 | | | | | | |
| | Other Detail | | | | | | | | | |
| L | | | | | |] <u> </u> | | | | |
| L | | | | Measur | e Sub Total | : | | | Sub Total: | |
| Ī | Field Notes: | | | | | | | | | |
| | ricia Notes. | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | Measure 8 Fix N | Moisture Problems | | | Compone | ents | | | | Inspected |
| | (Bas | ement/Crawlspace) 142 | 21 SQ. FT | • | • | | | | | |
| C | comment | | | | | | | | | |
| _ | | | | | Estimat | | _ | | Actual | |
| | Material / Labor | Description / Comment | Units | Qty | Unit Cost | To | al | Qty | Unit Cost | Total |
| 1 | Health and Safety Items | Moisture Barrier Needed | SqFt | 1 | | | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | | |
| | | | | | | | | | | |
| | Other Detail | | | | | | | | | |
| Ī | J | | | | | | | | | |
| L | | | | Measur | e Sub Total | : | | | Sub Total: | |
| | Field Notes: | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | Ments On | don O::- | and Totals | | | Cuan | d Total: | |
| | | | vvork Or | aer Gra | nd Total: | | | Gran | d Total: | |